

Cleanup Site Details

Cleanup Site ID: 8245

Cleanup Site ID: 8245	Facility/Site ID: 19772195	UST ID: 7917	Site Page	Site Documents	View Map
Cleanup Site Name: Lincoln Park 86					Glossary
Alternate Names: LINCOLN PARK 86, Seattle City Lincoln Park SW Dist					

LOCATION

Address: 7367 47TH SW			City: SEATTLE	Zip Code: 98136	County: King
Latitude: 47.53681	Longitude: -122.39289	WRIA: 9	Legislative District: 34	Congressional District: 7	TRS: 24N 3E 26

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? Yes
Statute: MTCA	NFA Date: 2/13/2012	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Lincoln Park 86	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Petroleum-Diesel	RB					
Petroleum-Gasoline	RB					
Petroleum-Other	RB					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		11/25/1997
LUST - Report Received	Completed		11/25/1997
Site Discovery/Release Report Received	Completed		11/25/1997
Initial Investigation / Federal Preliminary Assessment	Completed		3/8/2011
Site Status Changed to NFA	Completed		2/13/2012